

MRK	DATE	REVISION RECORD
△		
△		

SS-T BLACK BOX MOUNTING METHOD

Step 1(Figure 1):
Remove the rubber covers.




FIGURE 1

Step 2(Figure 2):
Use the tapping screws (T4x38) to fix the black box in place, then put back the rubber covers.

TAPPING SCREWS (T4X38)




FIGURE 2

NO.	DESCRIPTION		MATERIAL		FINISH (COLOR)	1	REMARK
DESIGN	CHECK	APPROVAL	⌀	G.TOL		Q'TY	
<i>Will</i>				±0.1	NAME	BLACK BOX	
Mar 25, 09			SCALE	UNIT	MODEL NO.	SS-T	FILE
SOUNDMAX® Electronics Limited					PART NO.		